Outdated Chrome version used by IoT device

Action

Severity Medium Status New Assignee Assign



DRXR14

IP: 10.203.64.22

Category: X-Ray Machine

Site: BMC OPC

Alert Events

Alert Detected

19:00, December 19, 2020

The usage of an outdated Chrome version has been detected on this device. Using older versions of a web browser can expose your device to security risks.

A deviation from the normal baseline was detected.

user agent	Mozilla/5.0 (Windows NT 10.0; Win64; x64) AppleWebKit/537.36 (KHTML, like Gecko) Chrome/68.0.3440.106 Safari/537.36

More Insights

Recommendation

- Update the browser to the latest version
- If browser usage on the device is authorized and essential, use a URL-filtering tool to block connections to known


malicious websites or update firewall policy rules to permit connections only to designated websites.

- Check network traffic coming to and from the device on the device details page and enable trusted behavior by applying an ACL (access control list) to restrict nonessential traffic.

Impacted Device

DRXR14


Risk Score 50



Category	X-Ray Machine
Profile	Carestream Mobile X-Ray Machine
Confidence Level	High
Confidence Score	99
Last Activity	09:02 December 21, 2020
Internet Access	Last Activity: 04:31 December 20, 2020

IDENTITY

Vendor	Carestream
Serial Number	7291
OS Group	Windows
OS Version	Windows 10
OS / Firmware Version	10
OS Support	Yes
AE Title	DRXR14
MAC Address	00:0e:8e:79:cd:75
IP Address	10.203.64.22
VLAN	252
Subnet	10.203.64.0/19
DHCP	Yes
Site	BMC OPC
International Access	No
Countries	
Listening Ports	80



Current Behaviors ⓘ

SECURITY

Risk Score	50
Anomaly Detection	Normal ⓘ
Baseline Modeling	
Anomaly Detection	Normal ⓘ

First Seen	13:54 June 26, 2020
Last Activity	09:02 December 21, 2020

Traffic Snapshot
18:00, December 13, 2020 - 18:00, December 20, 2020

Chart Type: **Detail View**